

FIG. 1

100




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12

170




FIG. 13

170

170




FIG. 15

170

170




FIG. 17

FIG. 14

FIG. 16



170




FIG. 18

170




FIG. 19

170




FIG. 20

PIDE Properties - PIDE_03

Parameters Tag

Vis	Name	Value	Type	Description
<input checked="" type="checkbox"/>	CVOverride	0.0	REAL	CV Override value
<input checked="" type="checkbox"/>	CVPrevious	0.0	REAL	CV Initialization val...
<input checked="" type="checkbox"/>	CVSetPrevious	0.000	REAL	CV Initialization requ...
<input checked="" type="checkbox"/>	CVManualLimit	0.000	REAL	Limit CV in manual mod...
<input checked="" type="checkbox"/>	CVManualMax	100.0	REAL	Maximum value for CV...
<input checked="" type="checkbox"/>	CVManualMin	0.0	REAL	Minimum value of CV...
<input checked="" type="checkbox"/>	CVHLimit	100.0	REAL	CV high limit value
<input checked="" type="checkbox"/>	CVLLimit	0.0	REAL	CV low limit value
<input checked="" type="checkbox"/>	CVROCLimit	0.0	REAL	CV rate of change limit...
<input checked="" type="checkbox"/>	FF	0.0	REAL	Feedforward value
<input checked="" type="checkbox"/>	FFPrevious	0.0	REAL	FF Initialization val...
<input checked="" type="checkbox"/>	FFSetPrevious	0.000	REAL	FF Initialization requ...
<input checked="" type="checkbox"/>	HandFB	0.0	REAL	CV Hand Feedback Val...
<input checked="" type="checkbox"/>	HandFBFault	0.000	REAL	HandFB value bad he...

Status: OK

Execution Order Number: 1

OK Cancel Apply Help

FIG. 21




FIG. 22




FIG. 24




FIG. 25